Date: October 27, 2026
Subject: Runway Alerts
Impacted: EGPWS Operators
Databases: 654 and Later

Dear Valued Customers,

AIP Runway data sources are used in the EGPWS Terrain Database to support the TAWS alerting algorithms and other advanced functions (e.g., RAAS). The AIP AIRAC cycle upon which each Terrain Database release cycle is based on is identified in the Release Statement. Airport changes, including new airports/runways, modified runway lengths and runway ID changes that are not reflected in the current Terrain Database release cycle may result in nuisance alerts until a subsequent release cycle.

The information below identifies the locations where airport/runway changes have been identified since the release of the most current database, and the possibility of nuisance alerts exists. Honeywell Aerospace's awareness of these changes is generally through AIP updates, NOTAMs and customer feedback.

Customers are advised to use the most current database available. For locations with the possibility of nuisance alerts due to runway data currency, customers are advised to provide operational guidance to pilots, including use of Terrain Inhibit if warranted.

Honeywell Aerospace remains committed to maximizing our awareness of airport/runway changes, whether reflected in current AIP data or anticipated in the near future, to the best of our ability, and working quickly to address discrepancies as soon as possible.

AIRAC cycle 2609 was used for TDB version 654, which was released on September 23, 2026. The following runway changes in the AIRAC cycle 2610 and 2611 have been identified and included in this notification.

ICAO	RWY	AIRPORT	COUNTRY	HONEYWELL AEROSPACE RESPONSE	PLANNED RESOLUTION
CYYY	RW06/24 & RW15/33	Mont-Joli	Canada	RW06/24- 06/24 changed to 05/23. Incorrect RAAS runway ID callouts. Runway 15/33 at this airport will be closed for operations. RAAS incorrect callouts (On ground).	TDB 655
EDDW	RW09/27	Bremen	Germany	RW09/27 – 09/27 Changed to 08/26. Incorrect RAAS runway ID callouts.	TDB 655

ICAO	RWY	AIRPORT	COUNTRY	HONEYWELL AEROSPACE RESPONSE	PLANNED RESOLUTION
EIKY	RW08/26	Kerry	Ireland	RW08/26 – 08/26 Changed to 07/25. Incorrect RAAS runway ID callouts.	TDB 655
EIWT	RW07/25	Weston	Ireland	RW07/25 – 07/25 Changed to 06/24. Incorrect RAAS runway ID callouts.	TDB 655
FWCL	RW10/28 & 15/33	Bakili Muluzi Intl	Malawi	ICAO code changed from FWCL to FWBM	TDB 655
KAEX	RW18/36	Alexandria	USA	The length of Runway 18/36 has been increased from 2,134 meters to 2,592 meters by relocating the RWY 18 threshold 458 meters to the north. RAAS Incorrect distance remaining advisories for RW36. 'On Taxiway' advisories during take-off roll from RW18 for the extended portion of the runway. TCF alerts may occur while landing on RW18.	TDB 655
KAZO	RW17/35	Kalamazoo/Battle Creek Intl	USA	The length of runway 17/35 has been increased from 1,983 to 2,119 meters by relocating RW35 threshold 136 meters to the south. RAAS Incorrect distance remaining advisories for RW17. 'On Taxiway' advisories during take-off roll from RW35 for the extended portion of the runway.	TDB 655

ICAO	RWY	AIRPORT	COUNTRY	HONEYWELL AEROSPACE RESPONSE	PLANNED RESOLUTION
KBTR	RW04L/22R & RW04R/22L	Baton Rouge Metro-Ryan	USA	RW04L/22R – 04L/22R Changed to 04/22. Incorrect RAAS runway ID callouts. Runway 04R/22L at this airport will be closed for operations. RAAS incorrect callouts (On ground).	TDB 655
KHDO	RW17L/35R & 17R/35L	Hondo Regl	USA	RW17L/35R – 17L/35R changed to 17/35. Incorrect RAAS runway ID callouts. Runway 17R/35L at this airport will be closed for operations. RAAS incorrect callouts (On ground).	TDB 655
KIKV	RW18/36	Ankeny Regl	USA	The length of Runway 18/36 has increased from 1,676 meters to 1,829 meters by relocating the RWY 18 threshold 153 meters to the north. RAAS Incorrect distance remaining advisories for RW36. 'On Taxiway' advisories during take-off roll from RW18 for the extended portion of the runway.	TDB 655
KLEB	RW18/36	Lebanon Mun	USA	The length of Runway 18/36 has increased from 1,585 meters to 1,646 meters by relocating the RWY 36 threshold 61 meters to the south. RAAS Incorrect distance remaining advisories for RW18. 'On Taxiway' advisories during take-off roll from RW36 for the extended portion of the runway.	TDB 655

ICAO	RWY	AIRPORT	COUNTRY	HONEYWELL AEROSPACE RESPONSE	PLANNED RESOLUTION
KSBY	RW14/32	Salisbury-Ocean City Wicomico	USA	The length of RWY 14/32 has been increased from 1,951 meters to 2,316 meters by relocating the RWY 32 threshold 365 meters toward the southeast. RAAS Incorrect distance remaining advisories for RW14. 'On Taxiway' advisories during take-off roll from RW32 for the extended portion of the runway.	TDB 655
KUES	RW10/28	Waukesha Co	USA	The length of the runway has been increased from 1,783 meters to 1,905 meters by extending the RWY 10 threshold 122 meters toward the west. RAAS Incorrect distance remaining advisories for RW28. 'On Taxiway' advisories during take-off roll from RW10 for the extended portion of the runway.	TDB 655
LFKF	RW05/23	Figari/Sud Corse	France	RW05/23- 05/23 changed to 04/22. Incorrect RAAS runway ID callouts.	TDB 655
LIRN	RW06/24	Capodichino	Italy	RW06/24 – 06/24 changed to 05/23. Incorrect RAAS runway ID callouts.	TDB 655
PAED	RW16/34	Elmendorf AFB	Alaska	The length of RWY 16/34 will be increased from 2,284 meters to 3,048 meters by relocating the RWY 16 threshold approximately 884 meters to the north and the RWY 34 threshold approximately 120 meters to the south. RW16/34 – 16/34 Changed to 17/35. Incorrect RAAS runway ID callouts.	TDB 655

ICAO	RWY	AIRPORT	COUNTRY	HONEYWELL AEROSPACE RESPONSE	PLANNED RESOLUTION
PAED (Cont.)	RW16/34	Elmendorf AFB	Alaska	Incorrect RAAS distance remaining advisories for RW17/35. 'On Taxiway' advisories during take-off roll from RW17 for the extended portion of the runway. TCF alerts may occur while landing on RW35.	TDB 655
RPMG	RW02/20	Philippines	Dipolog Principal	Runway 02/20 length has been increased from 1,884 meters to 2,038 meters. The runway 20 threshold has been displaced by 170 meters, and the RWY 02 threshold has been relocated 33 meters towards the ARP. Incorrect RAAS distance remaining advisories for RW02/20. 'On Taxiway' advisories during take-off roll from RW20 for the extended portion of the runway.	TDB 655
SAEZ	RW28	Ezeiza Intl/Ministro Pistarini	Argentina	As per AIP SUP A66/2026, RWY 29 THR will be relocated 1,450 meters west, and a temporary THR 28 will be established. The declared distances (TORA/TODA/ASDA/LDA) for both directions will be reduced to 1,850 meters. Effective 25-Oct-2026 through 11-Nov-2026. Incorrect RAAS distance remaining advisories for RW11. Incorrect RAAS runway ID callout for RW28.	TBD
UNBG	RW02/20	Gorno-Altaisk	Russia	The length of RWY 02/20 has changed from 2,301 meters to 2,151 meters due to the relocation of the RWY 02 threshold 150 meters toward the ARP as part of the runway reconstruction. Incorrect RAAS distance remaining advisories for RW20.	TDB 655

ICAO	RWY	AIRPORT	COUNTRY	HONEYWELL AEROSPACE RESPONSE	PLANNED RESOLUTION
VTUK	RW03/21	Khon Kaen	Thailand	Runway 03/21 length is temporarily reduced from 3,053 meters to 2,600 meters due to construction of Runway End Safety Areas (RESA), as per AIP SUP B 21/26 effective 01 Oct to 14 Dec 2026. **Phase 1:** RESA construction at RWY 03 (90 × 90 m) from 01 Oct – 31 Oct 2026. **Phase 2:** RESA construction at RWY 21 (240 × 90 m) from 01 Nov – 14 Dec 2026. Incorrect RAAS distance remaining advisories for RW03/21.	TBD
VVPC	RW15/33	Phu Cat	Vietnam	RW15/33 – 15/33 changed to 15L/33R Incorrect RAAS runway ID callouts. A new parallel runway, RWY 15R/33L, has been added to the left of RWY 15L/33R and will become operational effective 29-Oct-2026. Taxiway Landing caution while approaching for landing on the new RWY15R/33L, and 'On TWY' advisories during take-off roll.	TDB 655
YBRK	RW04/22	Rockhampton	Australia	As per AIP SUP H124/26, effective 29-Oct-2026, Runway 04/22 will be permanently decommissioned and reclassified as Taxiway N and apron area. RAAS incorrect callouts (On ground).	TDB 655
YBRY	RW10/28	Barimunya	Australia	RWY 10/28 has been extended by 60 meters at both ends. The added pavement has been designated as displaced threshold area. RAAS Incorrect distance remaining advisories for RW10/28. 'On Taxiway' advisories during take-off roll from RW10/28 for the extended portion of the runway.	TDB 655

Honeywell Aerospace

Following runway changes/database issues reported by the customer(s) or received from supplementary sources have been included in this notification.

ICAO	RWY	AIRPORT	COUNTRY	HONEYWELL AEROSPACE RESPONSE	PLANNED RESOLUTION
EINN	RW06/24	Shannon International	Ireland	As per NOTAM A3833/26, Effective from 26-Nov-26 the RWY 06/24 will be redesignated RWY 05/23. Incorrect RAAS runway ID callouts.	TDB 655
PHNL	RW08L/26R	Daniel K Inouye International	Hawaii	As per NOTAM # 09/151 (PHNL-A3917/26), Runway 08L/26R at PHNL has its eastern 1,637 meters closed. The declared distances for Runway 08L/26R are adjusted to 2,134 meters for TORA, TODA, ASDA, and LDA, effective from September 10, 2026, through November 12, 2026. RAAS Incorrect distance remaining advisories for RW08L.	TBD
RJBB	RW06L/24R	Kansai International	Japan	According to Japanese AIP SUP 247/26, which superseded AIP SUP 227/26, the length of Runway 06L/24R at Osaka Airport (RJBB) will be temporarily reduced from 4,000 m to 3,550 m due to the relocation of THR RWY 06L by 450 m toward the northeast. This change was originally planned for November 2026 under AIP SUP 227/26 but has been postponed to January 2027. RAAS Incorrect distance remaining advisories for RW24R. TCF alerts might occur while landing on RW06L.	TBD
SCCI	RW07/25	Carlos Ibanez Del Campo International	Chile	As per AIP SUP S18/2026, Due to works on runway 07/25 of the Carlos Ibanez Del Campo AP in Punta Arenas, from November 26, 2026, and for a period of approximately 18 months, RWY 07/25 will be closed and the parallel TWY (Alpha) will be enabled as RWY 08/26. ‘On Taxiway’ advisories during take-off roll from new runway 08/26.	TDB 655

ICAO	RWY	AIRPORT	COUNTRY	HONEYWELL AEROSPACE RESPONSE	PLANNED RESOLUTION
SCCI (Cont.)	RW07/25	Carlos Ibanez Del Campo International	Chile	Taxiway Landing caution while approaching for landing on the new RWY08/26, and 'On TWY advisories during take-off roll. Runway 07/25 at this airport will be closed for operations for a period of approximately 18 months. RAAS incorrect callouts (On ground).	TDB 655

Thank you,
Terrain Database Team

For the latest information regarding EGPWS databases, please visit:

https://ads.honeywellaerospace.com, click on TerrDB or E-mail: TerrDB@Honeywellaerospace.com

Database Accounts Services:
Phone : 1-800-247-0230 (US/Canada) or 1-602-436-6739, Select Option 5
E-mail : DSA@Honeywellaerospace.com

For OneNav+ tool related:
E-mail: OneNav@Honeywellaerospace.com
For 24-Hour/7-Day technical support, please contact the Technical Operations Center at 1-855-808-6500 (U.S. and Canada) or 1-602-365-6500 (Int'l), or contact Aero Technical Support.